







Front View







 Loose/broken/delaminated
 Damage/wear/hole

 Previous repair
 Replaced piece


Rear View



 Missing
 Spindles not original to desk


 Add-ons
 Inscriptions

Right Side




- | | |
|---|---|
| ■ Loose/broken/delaminated | ■ Previous repair |
| ■ Damage/wear/hole | ■ Replaced piece |

Left Side



- | | |
|---|--|
| ■ Missing | ■ Add-ons |
| ■ Spindles not original to desk | ■ Inscriptions |

Top



Loose/broken/delaminated

Damage/wear/hole

Previous repair

Replaced piece


Missing

Spindles not original to desk

Add-ons

Inscriptions


Bottom



■ Loose/broken/delaminated
■ Damage/wear/hole

■ Previous repair
■ Replaced piece

Bottom




■ Missing
■ Spindles not original to desk

■ Add-ons
■ Inscriptions

Drawer Front, Outer Surface



Rear Surface of Drawer Front



■ Loose/broken/delaminated

■ Damage/wear/hole

■ Previous repair

■ Replaced piece

■ Missing



■ Spindles not original to desk

■ Add-ons

■ Inscriptions

Inside Surface of Left Drawer Side

Inside Surface of Right Drawer Side



Loose/broken/delaminated

Damage/wear/hole

Previous repair

Replaced piece

Missing

Spindles not original to desk


Add-ons

Inscriptions

Rear Surface of Drawer Back



Front Surface of Drawer Back




■ Loose/broken/delaminated
■ Damage/wear/hole

■ Previous repair
■ Replaced piece


■ Missing
■ Spindles not original to desk

■ Add-ons
■ Inscriptions

Upper Surface of Drawer Bottom



Lower Surface of Drawer Bottom



■ Loose/broken/delaminated
■ Damage/wear/hole

■ Previous repair
■ Replaced piece

■ Missing
■ Spindles not original to desk

■ Add-ons
■ Inscriptions

Outside Surface, Right Drawer Side



Outside Surface, Left Drawer Side



Loose/broken/delaminated
 Damage/wear/hole

Previous repair
 Replaced piece

Missing
 Spindles not original to desk

Add-ons
 Inscriptions